

RAYMARINE SAFETY RECALL

SPX5 SPORT DRIVE PILOT and control head E12206

SPX5 SPORT DRIVE PILOT pilot only E12132



DESCRIPTION	CODE	ON SALE SINCE
SPX 5 Sport Drive Pilot and control head	E12206	6 February 2009
SPX 5 Sport Drive Pilot (pilot only)	E12132	6 February 2009

As customer safety is of paramount importance to Raymarine, we have decided to initiate a voluntary recall of this product. We have identified a potential component problem with the SPX5 Sport Drive Pilot product which we have sold between February and July 2009.

As a result the mechanical clutch assembly may fail, causing the steering of the vessel to lock in one direction, with a possible risk to the safety of the vessel and crew.

Customers must stop using the products immediately and arrange de-installation and return to the retailer/dealer from whom it was purchased.

The retailer/dealer will arrange for a replacement or, if preferred, a refund.

We are sorry for any inconvenience or concern caused.

No other products are affected by this recall.

Any customers who have any questions regarding these products should contact Raymarine Product Support at (603) 881-5200 or go to our website **www.raymarine.com**

Raymarine Inc.
16 July 2009

Raymarine[®]
...world leaders in marine electronics.