

Date: 22nd Jan 2016
Affected by this: 2500 Vertical and Horizontal Series
Created by: G.Barton
Subject: 3227 Plastic cap discontinued

Number: M232
Revision: 1
Pages: 1

The 3227 plastic cap as used on the top of the clutch nut on 2500 Vertical and horizontal models will be discontinued.

In the past this cap was used on 2200,2500,3500,4000 windlasses and 1500 capstans.

A stainless steel replacement for this plastic cap was introduced in 2012 and fitted to the SY 1500 and 4000 windlasses.

A decision was made to improve the appearance of all products by using this stainless steel cap, therefore all products will now use the stainless 7191 cap and the 3227 plastic cap will be discontinued.

As a result the 3227 plastic cap will no longer be available and is replaced by the 'P104750 - SS Cap (Ø49mm) and O-ring' kit which is a direct fit replacement.

The caps which are normally included with the 'P90005 – Seal Kit 2500/3500 Series' will be removed from the kit and not replaced, some retailers have images of this P90005 kit on their websites so a new image will be provided.



3227 Plastic Cap



P104750 SS cap (Ø49mm)
(7191 Stainless Steel Cap &
SP2790 O-ring)



P90005 Seal Kit